DPD-8904-59

30 December 1959

MEMORANDEM FOR: Chief, Materiel, DPD

: Photographic Equipment Malfunctions SUBJECT

: Staff Meeting Minutes, 14 Oct. 1958, dtd 16 Oct. 1958 REFERENCE

1. During the period 1 December 1959 through 30 December 1959 there were a total of seventeen (17) missions reported flown using photographic equipment. Equipments malfunctioned on one (1) of these missions giving an overall effectiveness of 94.02%.

2. Equipment reliability for the above referenced period was:

	A-1 Conf.	A-2 Conf.	B Conf.	Trackers
Missions Flown	o	1	5	15
Malfunctions	0	0	0	1
Per Cent Eff.	0	100%	100%	93.04

3. Tracker malfunction:

: sb

- a. Mission 8007 malfunction appeared to be caused by the metering switch.
- 4. Although tracker reliability has improved, all trackers are now going through overhaul and modification; two (2) at a time, at Perkin-Elmer. This will not impair our operational capability since each detachment will have five (5) trackers in place at all times.

SIENED Major. UHAF

25X1

25X1

DPD-DD/P Distribution:

0 - DPD/Mat

1 - Ch/DB/DFD

1 - DB/DPD

2 - RI/DPD